



Figure S1. Pitting corrosion in the dendritic region of low-density stainless steel.