

Supplementary Figure S1




Figure S1 - SEM micrographs of the epoxy surface.




Figure S2 - By naked eye visualization of CrN sample before and after electrochemical testing