metals

MDPI

Correction

Correction: Altshuler, T.L. The Brittle Fracture of Iron and Steel and the Sharp Upper Yield Point Are Caused by Cementite Grain Boundary Walls. *Metals* 2024, *14*, 871

Thomas L. Altshuler

Department of Mechanical Engineering, Northeastern University, Boston, MA 02115, USA; thomaslaltshuler@gmail.com

There were three errors in the original publication [1].

Equation (12) has been changed to the following:

$L = 1.273E(\gamma_s + \gamma_p)/\sigma_c^2$

In Sections 6.5 and 6.6, "Figure 13" has been changed to "Figure 12".

In Section 6.6, the formula "$_c = _y$ 560 MPa" has been changed to "$\sigma_c = \sigma_y$ = 560 MPa".

The authors state that the scientific conclusions are unaffected. This correction was approved by the Academic Editor. The original publication has also been updated.

Reference

1. Altshuler, T.L. The Brittle Fracture of Iron and Steel and the Sharp Upper Yield Point Are Caused by Cementite Grain Boundary Walls. *Metals* **2024**, *14*, 871. [CrossRef]

Disclaimer/Publisher's Note: The statements, opinions and data contained in all publications are solely those of the individual author(s) and contributor(s) and not of MDPI and/or the editor(s). MDPI and/or the editor(s) disclaim responsibility for any injury to people or property resulting from any ideas, methods, instructions or products referred to in the content.

check for updates

Received: 27 November 2024
Accepted: 28 November 2024
Published: 9 April 2025

Citation: Altshuler, T.L. Correction: Altshuler, T.L. The Brittle Fracture of Iron and Steel and the Sharp Upper Yield Point Are Caused by Cementite Grain Boundary Walls. *Metals* 2024, *14*, 871. *Metals* **2025**, *15*, 425. https://doi.org/10.3390/met15040425

Copyright: © 2025 by the author. Licensee MDPI, Basel, Switzerland. This article is an open access article distributed under the terms and conditions of the Creative Commons Attribution (CC BY) license (https://creativecommons.org/licenses/by/4.0/).