


Supplementary Figure S1. The diagram of data acquisition and processing in four steps. Three different lines in the same plot represent three different overload conditions. The data in the diagram comes from a representative participant.