
DLinear
iTransformer
a
Missed / false-alarm cost = 1:1
b
Missed / false-alarm cost = 2:1
c
Missed / false-alarm cost = 5:1
d
Missed / false-alarm cost = 10:1
Relative cost per 1000 windows
Alarm threshold on power risk score (MW)
0
200
400
600
800
250
500
750
1000
1250
1500
10
20
30
40