

Figure S1: **Real photos of the weighing balance from different viewpoints**. Legend of Abbreviations: LC = Load cell, MS = Metal support, UMP = Upper metal plate on which cages are placed, BMP = Bottom metal plate in tray shape, F = Fasteners to ensure LC. There is also a picture showing the red lamps turned on only during animal handling.