



# Article The Influence of Sample Size on Long-Term Performance of a 6σ Process

Andrei Alexandru Boroiu <sup>1</sup><sup>®</sup>, Aurel Mihail Titu <sup>2,</sup>\*<sup>®</sup>, Alexandru Boroiu <sup>1</sup><sup>®</sup>, Mihai Dragomir <sup>3</sup><sup>®</sup>, Alina Bianca Pop <sup>4,</sup>\*<sup>®</sup> and Stefan Titu <sup>5,6,</sup>\*<sup>®</sup>

- <sup>1</sup> Department of Road Vehicles and Transports, University of Pitesti, 1 Targul din Vale Street, 110040 Pitesti, Romania
- <sup>2</sup> Industrial Engineering and Management Department, Faculty of Engineering, "Lucian Blaga" University of Sibiu, 10 Victoriei Street, 550024 Sibiu, Romania
- <sup>3</sup> Design Engineering and Robotics Department, Robotics and Production Management, Faculty of Industrial Engineering, Technical University of Cluj-Napoca, 103-105 Muncii Blvd., 400641 Cluj-Napoca, Romania
- <sup>4</sup> Department of Engineering and Technology Management, Faculty of Engineering, Northern University Centre of Baia Mare, Technical University of Cluj-Napoca, 62A Victor Babes Street, 430083 Baia Mare, Maramures, Romania
- <sup>5</sup> The Oncology Institute "Prof dr Ion Chiricuță" Cluj Napoca, 34-36 Republicii Street, 400015 Cluj-Napoca, Romania
- <sup>6</sup> Faculty of Medicine, "Iuliu Hatieganu" University of Medicine and Pharmacy Cluj Napoca, 8 Victor Babes Street, 400000 Cluj-Napoca, Romania
- \* Correspondence: mihail.titu@ulbsibiu.ro (A.M.T.); bianca.bontiu@gmail.com (A.B.P.); stefan.titu@ymail.com (S.T.)

Abstract: There are many criticisms for the association between the Six Sigma concept and the two statistical metrics associated to  $6\sigma$  processes:  $1.5\sigma$  shift for maximum deviation and 3.4 PPM non-conformities for the long-term performance. As a result, the paper aims to carry out an analysis of this problem, and the first result obtained is that a stable process can reach a maximum drift, but its value depends on the volume of the sample. It is also highlighted that, using only the criterion "values outside the control limits" for monitoring stability through the Xbar chart, a minimum value can be calculated for the long-term performance of a process depending on the sample size. The main conclusion resulting from the calculations is that, in the case of a  $6\sigma$  process, the long-term performance is much better than the established value of 3400 PPB: For small volume samples of two pieces it is below 700 PPB, for three pieces it is below 200 PPB, and for samples with a volume greater than or equal to four pieces the performance already reaches values below 100 PPB! So, the long-term performance of  $6\sigma$  processes is certainly even better than the known value of 3.4 PPM.

Keywords: Six Sigma method; process stability; Xbar chart; process capability; 6σ process performance

# 1. Introduction

The Six Sigma method is an extremely well-known concept in quality theory, interpreted over time as a metric, methodology, or a management system.

The notation  $6\sigma$  is used when the approach is mathematical otherwise "Six Sigma" formula is used. In this way the difference is made between the capability index (mathematical concept) and the capability of the process (characteristic of the process).

As a methodology or a management system, there are two ways of implementation regarding the processes: DMAIC (Define, Measure, Analyze, Improve, Control) for quality improvement, and DMADV (Define, Measure, Analyze, Design, Verify) for the design of the process [1,2].

The lean manufacturing concept is associated with the Lean Six Sigma method [3–5] and involves the use of various quality-specific tools. There is a rich body of literature on



Citation: Boroiu, A.A.; Titu, A.M.; Boroiu, A.; Dragomir, M.; Pop, A.B.; Titu, S. The Influence of Sample Size on Long-Term Performance of a 6 $\sigma$ Process. *Processes* **2023**, *11*, 779. https://doi.org/10.3390/ pr11030779

Received: 1 February 2023 Revised: 23 February 2023 Accepted: 1 March 2023 Published: 6 March 2023



**Copyright:** © 2023 by the authors. Licensee MDPI, Basel, Switzerland. This article is an open access article distributed under the terms and conditions of the Creative Commons Attribution (CC BY) license (https:// creativecommons.org/licenses/by/ 4.0/). the Lean Six Sigma concept and its implementation [6–8], including following well defined logic schemes [3,9,10].

As a metric system, there are many possibilities for exploration, especially because of numerous criticisms [11–13], the most concrete being those that refer to the two statistical concepts associated with the method to characterize the long-term process: The  $1.5\sigma$  deviation shift and the proportion of non-conformities 3.4 PPM.

However, in order to understand how the Six Sigma method was created and its association with the two statistical quantities,  $1.5\sigma$  Shift and 3.4 PPM (parts per million) or 3400 PPB (parts per billion), it is important to present how the Six Sigma method appeared and evolved.

In order to overcome the problems due to the inadequate quality of the products, in 1986 the Motorola company initiated a quality improvement program under the guidance of the engineer Bill Smith [14–16], who proposed that the products had to be made more precisely in relation to the specification and established the following objective: For the essential characteristics to reach a superior precision, for which the limits of the tolerance interval (lower tolerance limit, LTL; upper tolerance limit, UTL) should be at a distance of  $\pm 6\sigma_{new}$  compared with the mean of the centered process. The old precision (corresponding to a minimum capability  $C_{pk} = 1.33$ ) assumed that the tolerance limits were only at a distance of at least  $\pm 4\sigma_{old}$  from the process average.

In accordance with the 3 sigma rule from statistical quality control, it is considered that no defects appear beyond the interval  $\pm 3\sigma$  compared with the average. The ratio between the domain situated beyond the tolerance interval where no defects appear (beyond  $\pm 3\sigma$  compared with average) and the size of the tolerance interval will increase from the value of 25% (result from the ratio  $\sigma_{old}/4\sigma_{old}$ ), to the value of 50% (result from the ratio  $3\sigma_{new}/6\sigma_{new}$ ). So it can be said that, in this way, the relative size of the safety zone is doubled.

Process precision is highlighted in Figure 1, where the following essential aspects can be observed: The improvement in quality is not made by widening the tolerance interval, but by improving the precision of the process, which is why two distributions of the values are represented in the image—the initial one (precision  $4\sigma_{old}$ ), and the new one (precision  $6\sigma_{new}$ ).



**Figure 1.** Improving the process precision: 6σ precision versus 4σ precision.

This is not as relevantly highlighted, even by the person who implement Bill Smith's idea and who is associated with the new concept—Michael Harry [15]—nor by other authors who present the origin of the concept [16,17].

The approach regarding increasing precision as an efficient way to improve quality is also supported by Montgomery [18], who says: "Quality is inversely proportional to variability". Likewise, Bass [19] states: "Variability: The source of defects".

However, this is the ideal case, which can be valid at an initial moment (immediately after adjusting the process), the so-called short-term performance, for which the proportion of non-conformities is  $2 \cdot F(6\sigma) = 2 \cdot 0.0001 = 0.0002$  PPM (parts per million), where F(x) is the integral Laplace function. In the long term, however, it must be accepted that the process will not remain perfectly centered, and it will have a certain drift in relation to the initial position.

Due to this idea, Bill Smith proposed adopting a process drift of  $1.5\sigma$ , shown in Figure 2. The choice of this value for the drift of the process was not scientifically argued, rather it was simply considered that the process reaches this value of the drift as a result of a possible special cause, after which the elimination of this special cause and the recentering of the process are carried out.



Figure 2. The concept  $1.5\sigma$  shift for the  $6\sigma$  process distribution.

Later, the second promoter of the new Six Sigma concept, Michel Harry, declared the shift  $1.5\sigma$  concept as the second pillar of the Six Sigma method, along with the first pillar—Six—into the phrase Six Sigma [15]. If the one who initially proposed the  $1.5\sigma$  value, Bill Smith, introduced it without justifying it scientifically, Michel Harry tried to justify it in various ways [15,20]: The influence of a random error—as a "drift" that all processes experience, a statistical correction or a dynamic mean off-set. However, all these justifications are strongly contested [12,13].

As a result, the "guaranteed" process performance has now been proposed as the proportion of products for the normal process beyond the  $4.5\sigma$  distance from the average (the proportion on the opposite side, beyond the  $6 + 1.5 = 7.5\sigma$  distance, is tiny, which is why it is neglected): The integral Laplace function  $F(4.5\sigma) = 3.4 \cdot 10^{-6}$  or 3.4 PPM. This value is accepted without reservations by most authors [21,22]. This is considered the long-term performance of the  $6\sigma$  process by many authors [15,22,23].

However, it is obvious that the process does not suddenly arrive from the initial state (perfectly centered) to the limit state (deviation  $1.5\sigma$ ), but passes through many intermediate states.

In fact, the process evolves from the most favorable state (perfectly centered) to the most unfavorable state (when it no longer meets the conditions to be considered stable), when it intervenes to eliminate the cause that made it unstable and it will be recentered.

All these states through which the process passes are states that must be associated with the concept of short-term Six Sigma performance, while for the evaluation of long-term Six Sigma performance it is correct to take into account the distribution of all intermediate states through which the process passes.

In the paper [24] this is taken into account and a rather elaborate calculation (of integral type) is made for the deviation that leads to 3.4 PPM non-conformities, but considering that the process mean drifts in a sinusoidal (sine-wave) pattern, based on Bill Smith's

representation for the drift of  $1.5\sigma$  and the animation for the distribution proposed, as justification by Michel Harry [15] but contested by Burns [13]. However, this cannot be true, because such a variation is unnatural, and it cannot be accepted for a statistical distribution.

All these considerations regarding long-term Six Sigma performance are in accordance with what is stated quite firmly [18,25,26]: One can speak of capability only when the stability of the process is ensured (and this is done with the help of the control chart), and the capability calculation is performed only in the situation when the distribution of the processed data is a normal distribution (which can be characterized by the normal law).

Since most works dedicated to the Six Sigma concept associate this concept with a maximum shift of  $1.5\sigma$  and a long-term performance of 3.4 PPM or 3400 PPB [23,24,27-29], it is obvious that this is only a short-term situation (although it is extreme—for the maximum drift), and the following question arises: For a  $6\sigma$  process (which keeps its standard deviation value unchanged over time, but which naturally has a drift over time, remaining stable), what is the proportion of long-term non-conformities (long-term performance of  $6\sigma$  processes)?

The way forward to obtain an answer to this question is the summation of all possible states through which a  $6\sigma$  process passes, under the conditions in which it is kept stable by using the control sheet.

Through the research presented below, a completely different result is obtained from that stated in the specialized literature, i.e., that the long-term performance of a process depends on the volume of the samples by which the stability of the process is ensured and for  $6\sigma$  processes it is much better than the established value of 3400 PPB: For samples with a volume greater than or equal to 4, the performance already reaches values below 100 PPB.

The remainder of this paper is organized as follows. Section 2 explores the relationship between the proportion of non-conformities of a  $6\sigma$  precision process in relation to the process deviation and to the sample size used to assure the process stability. In Section 4, the mathematical algorithm for calculating the proportion of non-conformities in the long term is built and is applied for various sizes of the sample used in the Xbar chart (for average). The conclusions are presented in the last section of the paper.

#### 2. Materials and Methods

There is a (double) infinity of combinations for the centering and the dispersion that a process can have at a given moment, which is why it is important to establish the meaning of a  $6\sigma$  process in the current study.

Thus, it is considered that the  $6\sigma$  process keeps its standard deviation value unchanged over time, but it can deviate from the initial position, within the limits in which it is maintained as a stable process. This scenario can be analyzed mathematically and the result is of interest for assessing the proportion of non-conformities of a  $6\sigma$  precision process in relation to the process deviation.

The other simple possibility of the evolution of the process that can be analyzed is the one in which the process remains perfectly centered, but loses its precision—this is the case that allows the determination of the inflated distribution for which PPM = 3.4.

The objective of this paper will be fulfilled by following the first scenario, but before this approach it is important to explore the second scenario as well, because the literature does not provide an answer to the exciting question: In the hypothesis that the process remains perfectly centered, how much should its dispersion increase for the percentage of non-conformities to increase from the initial value of 0.0002 PPM to the established value of 3.4 PPM?

This is another direction of evolution of the process accepted for defining long-term performance in some scientific works: The process is perfectly centered, but over time it reaches an inflated distribution [15,17]. In paper [17], the minimum  $C_{pk}$  is searched for, through ANOVA analysis, but it is correct to search for the inflated sigma corresponding to the value 3.4/2 = 1.7 PPM (because the distribution is perfectly centered), not for the value of 3.4 PPM, as presented in paper [15].

So, the answer will be: For the precision of the perfectly centered process, which leads to the established value of 3.4 PPM, the inverse of the Laplace function is searched for, which leads to the value  $3.4 \cdot 10^{-6/2} = 1.7 \cdot 10^{-6}$ .

The result can be obtained using the tables of the Laplace function, but it is easier using the NORM.DIST function from the Microsoft Excel program through successive attempts. Following this, the result of 1.7 PPM is obtained for the variable x = -4.645:

$$NORM.DIST(-4.645, 0, 1, TRUE) = 1.7PPM$$
(1)

So, when the process (which is kept centered) reaches an "inflated distribution" of 6/4.645 = 1.2917 (rounded: 1.3), higher than that of the initial value  $\sigma$ , the proportion of non-conformities will be 3.4 PPM.

So the 3.4 PPM concept can be associated with a perfectly centered process of precision  $4.645\sigma$  (with an inflated sigma 1.3 times higher than the initial one, corresponding to the  $6\sigma$  process).

Exploring the first scenario (the  $6\sigma$  process keeps its standard deviation value unchanged over time, but it deviates in time) demonstrates it is the most prolific. In addition, within it, the possibility of analyzing the most concrete scenario can be seen: Considering the constant precision ( $6\sigma$ ), i.e., the "precision of the  $6\sigma$  process", it can calculate the PPM depending on the sample volume (based on the control sheet for the average, which ensures the stability of the process).

Therefore, the analysis can only be done in relation to a single criterion for tracking the stability with the control chart: Placing the process within the control limits (the other criteria, supplementary run-rules—e.g., not to be more than 9 points consecutively increasing or decreasing, or not to be above/below the average—cannot be taken into account simultaneously; an analysis based only on them is presented in the paper [20]).

It is obvious that in the long term the process evolves between the limits known from the control sheet [30,31], and when it exceeds one of them it is recentered, so the long-term performance of the process is somewhere between the situation when the performance process  $6\sigma$  is perfectly centered (which means 2.0.001 PPM = 0.002 PPM) and the situation when the process is at the limit of becoming "out of control".

The control limit should not be at a distance of  $\pm 1.5\sigma$  from the average. The distance depend on the method by which the stability of the process is monitored. As a rule, the "Xbar–Range" control sheet is used, where the limits for the average are at a distance that depends on the volume of the sample, according to Lyapunov's theorem [31]:

$$Shift_{max} = 3 \cdot \sigma_{mean} = 3 \cdot \frac{\sigma_x}{\sqrt{n}} = \frac{3}{\sqrt{n}} \cdot \sigma_x \tag{2}$$

where *n* is sample volume.

This is the maximum shift of the process,  $Shift_{max}$ , or maximum drift (deviation),  $D_{max}$ . For example, the following figure shows the distribution of means for two cases (Figure 3):

• for n = 4:

$$n = 4 \Longrightarrow \sigma_{mean} = \frac{\sigma_x}{\sqrt{4}} = \frac{\sigma_x}{2} \Longrightarrow Shift_{max} = 3\sigma_{mean} = 1.5\sigma_x \tag{3}$$

• for n = 9:

$$n = 9 \Longrightarrow \sigma_{mean} = \frac{\sigma_x}{\sqrt{9}} = \frac{\sigma_x}{3} \Longrightarrow Shift_{max} = 3\sigma_{mean} = \sigma_x \tag{4}$$



**Figure 3.** Average distribution for centered  $6\sigma$  processes, for n = 4 and n = 9.

It is known that even if the Median chart is used to ensure the stability of the processes, things are very similar [18,24,30], so the conclusions that will be obtained for the analysis performed with the Xbar chart will also be valid in the case of using other control charts.

For values of the sample size n from 2 to 10, for the maximum drift (or shift) of the process, the values resulting from relation (2), expressed in  $\sigma_x$  units, are highlighted in Figure 4.



Figure 4. The dependence of the maximum drift on the sample volume n.

The graph  $D_{max}(n)$  reveals that the maximum deviation of the process decreases as the volume of samples used in monitoring the process increases (for example, for n = 4 it is  $1.5\sigma_x$ , and for n = 9 it decreases to  $\sigma_x$ )—Figure 4.

Relation (2) is used in the same way by Gupta [32], who found the same values. However, the determination of these values can be done in another way. Bothe [33] takes into account sample volumes from 1 to 6, and calculates the drift value for the average at which the probability of discovering the exceeding of the control limits (thus the loss of process stability) is 0.5.

The most used indicator for evaluating the capability of a process is the capability index  $C_{pk}$ , because it has a simple analytical expression and is relevant enough, although there are other indicators that can characterize the capability of the process better, such as the Taguchi Capability Index, but which imply much more elaborate calculation [34].

Therefore, considering that the distribution of the data is also normal (it would not be mandatory, but so that the calculation algorithm below can be used), this being the most

common situation, results in one more particularly interesting aspect: It is clear that, in any situation, the potential capability  $C_p$  will be

$$C_{\rm p} = 12\sigma/6\sigma = 2.0,\tag{5}$$

Instead, but the capability index  $C_{pk}$  will depend on the drift or shift, so on the sample size being able to have values from

$$C_{vk} \equiv C_v = 2.0 \tag{6}$$

when the distribution of values is perfectly centered, up to the minimum value of

$$C_{pk,min} = \frac{6\sigma - Shift_{max}}{3\sigma} = \frac{6\sigma - \frac{3}{\sqrt{n}}\sigma}{3\sigma} = 2 - \frac{1}{\sqrt{n}}$$
(7)

when the distribution occupies the extreme value (left or right).

So:

$$C_{pk} = \left(2 - \frac{1}{\sqrt{n}}\right) \dots 2.0\tag{8}$$

Thus, it is possible to calculate and graphically represent  $C_{pk,min}$  as a function of sample size n, by relation (7), for the usual values n = 2...10 (Figure 5).



Figure 5. The dependence of the minimum capability index  $C_{\mathrm{pk}}$  on the sample volume n.

In addition, in paper [33] this reasoning based on relation (7) can be found, but applied for  $C_p = 1.33$  (when the tolerance interval is  $\pm 4\sigma_x$ ) for the comparative analysis of the effective capability obtained for two values of the sample volume: n = 4 versus n = 6. In this work,  $C_{pk,min}$  is considered  $C_{pk}$ : the so-called *dynamic*  $C_{pk}$  index.

Park [20] also states that the capability is dependent on the sample volume, but he does a study not in relation to the "exceeding the control limits" criterion but in relation to the "supplementary run-rule".

It is observed that, by increasing the volume of the sample, the increase of  $C_{pk}$  is obtained, and starting with volume samples 3 and 4,  $C_{pk}$  already exceeds the value of 1.33, generally considered as the lower limit in series production.

This means that for samples of rather small volumes (from n = 3 upwards) the Six Sigma concept "guarantees" a minimum capability above the value of  $C_{pk} = 1.33$ , and only in the particular case n = 4 is the well-known value of  $C_{pk} = 1.5$  obtained.

Based on the central limit theorem, regardless of the distribution of the analyzed characteristic, the distribution of the sample means approaches the normal law (the more the number of data is larger).

If the characteristic distribution is considered to be normal (as it is considered within the Six Sigma method), the opportunity arises to evaluate the proportion of non-conformities depending on how the stability of the process is ensured (depending on the volume n of the samples; usually n can have values of to 2 to 10, but most frequently n = 3, 4 or 5), according to the algorithm presented below.

# 3. Results

The distribution of the mean is considered within the range of  $\pm 3\sigma_{\overline{\chi}}$  compared with

the mean of the means  $\overline{X}$  (as is worked out on the control sheet for the mean, where the control limits are, according to the 3 sigma rule, at a distance of  $\pm 3\sigma_{\overline{X}}$  compared with the mean), with  $\sigma_{\overline{X}} = \frac{\sigma_x}{\sqrt{n}}$ , where n is the sample size (according to Lyapunov's theorem [31]).

The distribution is centered ( $\overline{X}$  is identical to half of the tolerance range  $\pm 6\sigma_x$ ), with  $\sigma_{\overline{X}} = \frac{\sigma_x}{\sqrt{n}}$ , where n is the sample size. In Figure 6, it is exemplified for the case of volume samples n = 4, when  $\sigma_{\overline{X}}(n = 4) = \frac{\sigma_x}{\sqrt{4}} = \frac{\sigma_x}{2}$ .



The graphs of sample frequencies and sample means, for n = 4

**Figure 6.** The distribution of the means and the distribution of the variable x for a certain value of the mean, for sample size n = 4.

Our study takes into account the normed normal law: The number of steps m is adopted and the domain of definition of the normed normal distribution for the mean (-3, 0) is discretized with the corresponding working step,  $\Delta x = 3/m$ , and the calculation will be made for half of the domain of definition, given that the normal function is symmetric, so the result obtained must finally be multiplied by 2.

In order to cover the entire theoretical domain of definition  $(-\infty, 0)$ , which represents 50% of the distribution, (1 + m) steps are used: Thus, for  $i = 0 \dots m$ , the values are calculated:

$$x_i = -3 + i \cdot \frac{3}{m} = -3\left(1 - \frac{i}{m}\right), \ i = 0 \dots m,$$
(9)

for which the corresponding Laplace integral function is calculated (the area under the f(x) curve to the left of each  $x_i$  value) using the NORM.DIST function available in the Microsoft Excel software:

$$F(x_i) = NORM.DIST(x_i, 0, 1, TRUE), \ i = 1...m,$$
(10)

and for *i* = 0 the value will be considered  $F(x_0) = 0$ .

The area of each surface element of width  $\Delta x$  under the mean distribution graph (see Figure 6) will be calculated with the relation:

$$A_{element,i} = F(x_{i+1}) - F(x_i), \ i = 0...m$$
(11)

As for a certain sample size n, between the mean square deviation of the mean of the samples  $\sigma_m$  and the mean square deviation of the analyzed characteristic  $\sigma_x$ , there is the relationship:

$$\sigma_m = \frac{\sigma_x}{\sqrt{n}} \tag{12}$$

If the notation is used

$$k = \frac{3}{\sqrt{n}} \tag{13}$$

the distances from the tolerance limits (ie  $\pm 6\sigma_x$ ) of these surface elements of the media distribution will be:

• the distance to the near limit, on the left  $(-6\sigma_x)$ :

$$d_{l,i} = \left(6 - \frac{3}{\sqrt{n}}\right) + i \cdot \Delta \mathbf{x} = (6 - \mathbf{k}) + \mathbf{i} \cdot \frac{\mathbf{k}}{m}$$
(14)

• the distance from the far limit, on the right  $(+6\sigma_x)$ :

$$d_{r,i} = 12 - d_l \tag{14'}$$

The proportion of non-conformities (values beyond  $\pm 6\sigma_x$  limits) corresponding to the two distances consists of the following two "queues":

$$Q_{l,i} = 1 - \text{NORM.DIST}(d_{l,i}, 0, 1, \text{TRUE})$$
 (15)

$$Q_{r,i} = 1 - \text{NORM.DIST}(d_{r,i}, 0, 1, \text{TRUE})$$
 (15')

As a result, for a surface element of the distribution of means (slice), the proportion of non-conformities (values beyond the  $\pm 6\sigma_x$  limits) will be proportional to the area under the mean frequency curve  $f(\overline{X})$  for that element:

1—values smaller than  $-6\sigma_x$  (the near limit, on the left):

$$P_{l,i} = A_{element,i} \cdot Q_{l,i} \tag{16}$$

2—values greater than  $6\sigma_x$  (the far limit, on the right):

$$P_{r,i} = A_{element,i} \cdot Q_{r,i} \tag{16'}$$

For the respective surface element, the proportion of non-conformities will be the sum:

$$P_{element,i} = P_{l,i} + P_{r,i} \tag{17}$$

For half of the normal distribution of the mean, the total proportion of non-conformities is obtained by summing the (1 + m) calculation elements, and for the entire distribution (which is a symmetric distribution) the amount obtained is doubled, i.e.:

$$P_x = 2 \cdot \sum_{i} P_{element,i} \tag{18}$$

Using the facilities of the Microsoft Excel program, the calculation was made for each size n of the sample,  $n = 2 \dots 10$ , for a certain predetermined work step, according to the following logical scheme (Figure 7):



Figure 7. The flowchart for the calculation program created with Microsoft Excel software.

The final results obtained for the finest work steps (0.1; 0.05; 0.02; 0.01), to obtain the smallest surface elements, are presented in Table 1 (where the proportion of nonconformities parts per billion (PPB) has been rounded to the nearest whole number) and are graphically represented in Figure 8.

Before interpreting the obtained results, it is necessary to evaluate how much the step used matters for the accuracy of the calculations.

The working method, of course, has an inherent error, given by the fact that the discretization domain of the sample means was limited to  $\pm 3$  compared with the mean for the normalized normal distribution, and by the limitation of the number of steps (the finest discretization was for 300 steps).

	Proportion of Non-Conformities							
Sample Size, n	Step = 0.1 (30 + 1) Steps		Step = 0.05 (60 + 1) Steps		Step = 0.02 (150 + 1) Steps		Step = 0.01 (300 + 1) Steps	
	Per Units	PPB	Per Units	PPB	Per Units	PPB	Per Units	РРВ
2	$5.77081 \cdot 10^{-7}$	577	$6.13154 \cdot 10^{-7}$	613	$6.36392 \cdot 10^{-7}$	636	$6.44419 \cdot 10^{-7}$	644
3	$1.39784 \cdot 10^{-7}$	140	$1.47967 \cdot 10^{-7}$	148	$1.53206 \cdot 10^{-7}$	153	$1.5501 \cdot 10^{-7}$	155
4	$6.00674 \cdot 10^{-8}$	60	$6.336 \cdot 10^{-8}$	63	$6.54582 \cdot 10^{-8}$	65	$6.6179 \cdot 10^{-8}$	66
5	$3.41757 \cdot 10^{-8}$	34	$3.5932 \cdot 10^{-8}$	36	$3.70472 \cdot 10^{-8}$	37	$3.74297 \cdot 10^{-8}$	37
6	$2.28138 \cdot 10^{-8}$	23	$2.3915 \cdot 10^{-8}$	24	$2.46124 \cdot 10^{-8}$	25	$2.48513 \cdot 10^{-8}$	25
7	$1.68319 \cdot 10^{-8}$	17	$1.75967 \cdot 10^{-8}$	18	$1.808 \cdot 10^{-8}$	18	$1.82454 \cdot 10^{-8}$	18
8	$1.32781 \cdot 10^{-8}$	13	$1.38474 \cdot 10^{-8}$	14	$1.42065 \cdot 10^{-8}$	14	$1.43293 \cdot 10^{-8}$	14
9	$1.0979 \cdot 10^{-8}$	11	$1.14242 \cdot 10^{-8}$	11	$1.17046 \cdot 10^{-8}$	12	$1.18004 \cdot 10^{-8}$	12
10	$9.39479 \cdot 10^{-9}$	9	$9.7559 \cdot 10^{-9}$	10	$9.9831 \cdot 10^{-9}$	10	$1.00607 \cdot 10^{-8}$	10

**Table 1.** The values for parts per billion, for  $n = 2 \dots 10$ , obtained for different work steps.



**Figure 8.** The graphs PPB(n) for  $n = 2 \dots 10$  and various step sizes.

Analyzing the data in Table 1 and the four graphs in Figure 8, it was found that, for these reduced values of the step, relatively small different values were obtained, which means that at this level of detail the errors of the method are acceptable, and, therefore, the results obtained for the smallest step (0.01) will be used for interpretation (Figure 9).

It was found that, by increasing the fineness of the step, not much was gained in the precision aspect, so the values obtained with the finest step, of 0.01, came close enough to the exact values that would result from integral calculation, so the conclusions that are formulated are absolutely justified in this regard.

The obtained results will not change significantly for a finer step, so conclusions can be formulated based on the values obtained for the finest step and represented in Figure 9.



**Figure 9.** The graph PPB(n) for  $n = 2 \dots 10$  and for step size p = 0.01.

It is obvious that the results obtained are significantly different from the value of 3400 PPB, which is accepted by most authors [15,23,24,27–29] or disputed by other authors [11–13] who do not propose another solution.

It is very interesting that, in order to obtain a substantial increase in long-term capability, it is effective to use not very large samples: Following the graph in Figure 9, it can be stated that the most recommended is the sample of size n = 4, which leads at a long-term capability below 100 PPB (and by no means known value of 3400 PPB).

Better values were found for the long-term performance of the  $6\sigma$  process as larger volume of samples were used to ensure the stability of the process.

## 4. Conclusions

It is found that, for 6 $\sigma$  processes, two long-term scenarios can be analyzed:

- 1. the precision of the process is maintained at the level of  $6\sigma$ , but over time a drift of the process occurs, which can reach values that depend on the volume of the sample used in the control sheet through which the stability of the process is monitored;
- 2. the process remains perfectly centered, but the standard deviation increases over time (inflated distribution); in this case, the 3.4 PPM level is obtained for an increase of 1.3 times the standard deviation, and the tolerance limits (both) are reached at distances of  $4.645\sigma_{inflated}$ .

Exploring the first scenario (the  $6\sigma$  process keeps its standard deviation value unchanged over time, but it deviates in time) is the most prolific, so that the main research followed this path.

The results obtained regarding the maximum drift  $Shift_{max}$  and the capability, characterized by the  $C_{pk}$  index, are in accordance with what other authors have studied (they have values that depend on the volume of the sample), but they are presented in a very clear way and for a wide range of values of the sample size, both as analytical relations and as graphic representations.

Our contribution is the fact that the following original statement is argued: It is true that, by ensuring the stability of the process by using the control sheet for the average, the process can reach a maximum drift of Shift<sub>max</sub> =  $\frac{3}{\sqrt{n}}$ , but this is not the long-term performance of the process—it is still a short-term performance, the lowest, at the time when the adjustment will intervene and the process will be recentered, which will have the best short-term performance at this moment.

It was also highlighted that by using only one of the criteria for monitoring stability through the Xbar chart (the one that appears most frequently and can be exploited mathematically: The appearance of values outside the control limits, without taking into account the supplementary run-rules), a minimum value can be calculated for the long-term performance of a process depending on the volume of samples used for the control sheet.

The main conclusion resulting from the calculations is that, in the case of a  $6\sigma$  process, the long-term performance is better than the established value of 3400 PPB: For small volume samples, of two pieces, it is below 700 PPB; for three pieces it is below 200 PPB; and for samples with a volume greater than or equal to four the performance already reaches values below 100 PPB.

Moreover, these values, obtained only on the basis of a single stability monitoring criterion (exceeding the control limits), are coverage values, i.e., the performance of the  $6\sigma$  processes is definitely even better. Thus, for the most common case, which is associated with a 1.5 $\sigma$  shift (when the sample volume is n = 4) and a value of 3400 PPB, with certainty for the  $6\sigma$  process the proportion of non-conformities is below 100 PPB.

The research was based on only one criterion for evaluating the stability of the  $6\sigma$  processes, although the most important one—exceeding the control limits for the average. The most promising direction for research development is the simultaneous consideration of several process stability evaluation criteria, which will surely lead to even better values for long-term performance of  $6\sigma$  processes.

These results obtained in the current research will further motivate the researchers and practitioners in the field of quality to consider keeping the stability of the processes under control as a priority, along with ensuring the highest possible precision of the process.

**Author Contributions:** Conceptualization: A.B., A.A.B. and S.T.; methodology: A.M.T. and A.B.; software: A.B. and S.T.; validation: A.M.T. and M.D.; formal analysis: A.A.B.; investigation, A.B.P.; resources: A.M.T. and A.B.; data curation: A.B.P. and S.T.; writing-original draft preparation: A.B. and A.M.T.; writing—review and editing: A.M.T.; visualization, A.M.T. and M.D.; supervision: A.M.T.; project administration: A.B.P. and S.T. All authors have read and agreed to the published version of the manuscript.

Funding: This research received no external funding.

Institutional Review Board Statement: Not applicable.

Informed Consent Statement: Not applicable.

Data Availability Statement: Not applicable.

Conflicts of Interest: The authors declare no conflict of interest.

## References

- Yang, C.-C.; Jou, Y.-T.; Lin, M.-C.; Silitonga, R.M.; Sukwadi, R. The Development of the New Process of Design for Six Sigma (DFSS) and Its Application. *Sustainability* 2022, 14, 9294. [CrossRef]
- Palací-López, D.; Borràs-Ferrís, J.; da Silva de Oliveria, L.T.; Ferrer, A. Multivariate Six Sigma: A Case Study in Industry 4.0. Processes 2020, 8, 1119. [CrossRef]
- 3. Huang, C.-Y.; Lee, D.; Chen, S.-C.; Tang, W. A Lean Manufacturing Progress Model and Implementation for SMEs in the Metal Products Industry. *Processes* **2022**, *10*, 835. [CrossRef]
- 4. Sá, J.C.; Reis, M.; Dinis-Carvalho, J.; Silva, F.J.G.; Santos, G.; Ferreira, L.P.; Lima, V. The Development of an Excellence Model Integrating the Shingo Model and Sustainability. *Sustainability* **2022**, *14*, 9472. [CrossRef]
- 5. Jou, Y.-T.; Silitonga, R.M.; Lin, M.-C.; Sukwadi, R.; Rivaldo, J. Application of Six Sigma Methodology in an Automotive Manufacturing Company: A Case Study. *Sustainability* **2022**, *14*, 14497. [CrossRef]
- 6. Yadav, G.; Desai, T.N. Lean Six Sigma: A categorized review of the literature. Int. J. Lean Six Sigma 2016, 7, 1. [CrossRef]
- Gavriluță, A.C.; Niţu, E.L.; Gavriluță, C.A. Algorithm to Use Some Specific Lean Manufacturing Methods: Application in an Industrial Production Process. Processes 2021, 9, 641. [CrossRef]
- Yadav, G.; Seth, D.; Desai, T.N. Application of hybrid framework to facilitate lean six sigma implementation: A manufacturing company case experience. *Prod. Plan. Control* 2017, 29, 185–201. [CrossRef]
- Wang, F.-K.; Rahardjo, B.; Rovira, P.R. Lean Six Sigma with Value Stream Mapping in Industry 4.0 for Human-CenteredWorkstation Design. Sustainability 2022, 14, 11020. [CrossRef]
- 10. Yadav, G.; Seth, D.; Desai, T.N. Analysis of research trends and constructs in context to lean six sigma frameworks. *J. Manuf. Technol. Manag.* **2017**, *28*, 794–821. [CrossRef]
- 11. Available online: https://en.wikipedia.org/wiki/Six\_Sigma (accessed on 4 January 2023).

- 12. Wheeler, D.J. The Six Sigma Practitioner's Guide to Data Analysis, 3rd ed.; SPC Press: Knoxville, TN, USA, 2003.
- 13. Burns, A.D. Six Sigma: Lessons from Deming. 2007. Available online: http://q-skills.com/papers/6sDeming.htm (accessed on 4 January 2023).
- 14. Available online: https://www.qualitygurus.com/history-of-six-sigma/ (accessed on 4 January 2023).
- 15. Harry, M. Resolving the Mysteries of Six Sigma: Statistical Constructs an Engineering Rationale; Palladyne Publishing: Phoenix, AZ, USA, 2003.
- 16. Pochampally, K.K.; Gupta, S.M. Six Sigma Case Studies with Minitab; Taylor & Francis Group: Boca Raton, FL, USA, 2014; ISBN 78-1-4822-0559-6.
- 17. Raval, N.; Muralidharan, K. A Note on 1.5 Sigma Shift in Performance Evaluation. *Int. J. Reliab. Qual. Saf. Eng.* **2016**, 23, 1640007. [CrossRef]
- Montgomery, D.C. Introduction to Statistical Quality Control, 6th ed.; Arizona State University: Tempe, AZ, USA; John Wiley & Sons, Inc.: Hoboken, NJ, USA, 2009; ISBN 78-0-470-16992-6.
- 19. Bass, I. Six Sigma Statistics with Excel and Minitab; The McGraw-Hill Companies, Inc.: New York, NY, USA, 2007; ISBN 0-07-154268-X.
- 20. Park, J.H. A Note for 1.5 Shift of Six Sigma. J. Soc. Korea Ind. Syst. Eng. 2022, 45, 1. [CrossRef]
- Hernández-Lara, A.-B.; Sánchez-Rebull, M.-V.; Niñerola, A. Six Sigma in Health Literature, What Matters? Int. J. Environ. Res. Public Health 2021, 18, 8795. [CrossRef] [PubMed]
- 22. Tseng, C.-C.; Chiou, K.-C.; Chen, K.-S. Estimation of the Six Sigma Quality Index. Mathematics 2022, 10, 3458. [CrossRef]
- 23. Voelkel, J. What is 3.4 Parts Per Million? Rochester Institute of Technology: Rochester, NY, USA, 2014.
- 24. AIAG. Statistical Process Control (SPC), 2nd ed.; Automotive Industry Action Group: Southfield, MI, USA, 2005.
- Lemke, J.; Kijewska, K.; Iwan, S.; Dudek, T. Six Sigma in Urban Logistics Management—A Case Study. Sustainability 2021, 13, 4302. [CrossRef]
- 26. Sujova, A.; Simanova, L.; Marcinekova, K. Sustainable Process Performance by Application of Six Sigma Concepts: The Research Study of Two Industrial Cases. *Sustainability* **2016**, *8*, 260. [CrossRef]
- Stanivuk, T.; Gvozdenović, T.; Žanić Mikuličić, J.; Lukovac, V. Application of Six Sigma Model on Efficient Use of Vehicle Fleet. Symmetry 2020, 12, 857. [CrossRef]
- Pfeifer, M.R. SMEs in Automotive Supply Chains: A Survey on Six Sigma Performance Perceptions of Czech Supply Chain Members. *Processes* 2022, 10, 698. [CrossRef]
- 29. Pyzdek, T.; Keller, P. *The Six Sigma Handbook: A Complete Guide for Green Belts, Blacks Belts, and Manager at All Levels,* 3rd ed.; McGraw-Hill Companies: New York, NY, USA, 2010.
- 30. Oakland, J.S. Statistical Process Control, 5th ed.; Elsevier Science Linacre House: Jordan Hill, Oxford, UK, 2003; ISBN 0 7506 5766 9.
- Boroiu, A. Instrumente Statistice Utilizate în Managementul Calității. University of Piteşti Publishing House: Piteşti, Romania, 2010; ISBN 978-606-560-108-6.
- Gupta, P. The 1.5 Sigma Shift Explained. Available online: https://www.researchgate.net/publication/294260437\_The\_15 \_Sigma\_Shift\_Explained (accessed on 4 January 2023).
- 33. Bothe, D.R. Statistical reason for the 1.5 s shift. Qual. Eng. 2002, 14, 479–487. [CrossRef]
- Yu, C.-M.; Huang, T.-H.; Chen, K.-S.; Huang, T.-Y. Construct Six Sigma DMAIC Improvement Model for Manufacturing Process Quality of Multi-Characteristic Products. *Mathematics* 2022, 10, 814. [CrossRef]

**Disclaimer/Publisher's Note:** The statements, opinions and data contained in all publications are solely those of the individual author(s) and contributor(s) and not of MDPI and/or the editor(s). MDPI and/or the editor(s) disclaim responsibility for any injury to people or property resulting from any ideas, methods, instructions or products referred to in the content.