



Parts List	
Part No	Subassembly Name
2100	Z-Axis Actuation
2200	X-Axis Actuation
2300	Hand Drill
2400	Microscope Imaging Assembly
2500	Spacer Assembly
2600	Electronics Box
2700	Custom Experiment Setup
2800	Optomechanical Alignment Subassembly

