

Article

A Survey on the Oxidation Behavior of a Nickel-Based Alloy Used in Natural Gas Engine Exhaust Valve Seats

José Henrique Alano ^{1,*}, Renato Luiz Siqueira ², Claudio Beserra Martins Júnior ³, Rodrigo Silva ³, Guilherme dos Santos Vacchi ³ and Carlos Alberto Della Rovere ^{3,*}

¹ Engineering School, Federal University of Rio Grande, Avenida Itália, km 8—Bairro Carreiros, Rio Grande 96203-900, Brazil

² Latin American Institute of Technology, Infrastructure and Territory, Federal University of Latin American Integration, Avenida Tancredo Neves 6731, Foz do Iguaçu 85867-970, Brazil

³ Munir Rachid Corrosion Laboratory, Department of Materials Engineering, Federal University of São Carlos, Rodovia Washington Luís, Km 235, São Carlos 13565-905, Brazil

* Correspondence: henrique.al@gmail.com (J.H.A.); rovere@ufscar.br (C.A.D.R.); Tel.: +55-53-3237-3091 (J.H.A.); +55-16-3351-8525 (C.A.D.R.)

Supplementary material




Figure S1. Mass variation per unit surface area as a function of the exposure time for the SV15 alloy at 740 °C: A) $\log y$ versus $\log t$ to determine the oxidation rate index (n); and B) y versus t to determine the linear oxidation rate constant (K_1).




Figure S2. Regression lines two-stages at 900 °C.



Disclaimer/Publisher's Note: The statements, opinions and data contained in all publications are solely those of the individual author(s) and contributor(s) and not of MDPI and/or the editor(s). MDPI and/or the editor(s) disclaim responsibility for any injury to people or property resulting from any ideas, methods, instructions or products referred to in the content.