Patina Formation and Aesthetic Durability of Architectural Copper and Copper Alloys in the Marine–Desert Environment of Dubai

Inger Odnevall[1,2,3*] and Gunilla Herting[1]

[1] KTH Royal Institute of Technology, School of Engineering Sciences in Chemistry, Biotechnology and Health, Department of Chemistry, Division of Surface and Corrosion Science, Stockholm, Sweden
[2] AIMES–Center for the Advancement of Integrated Medical and Engineering Sciences at Karolinska Institute and KTH Royal Institute of Technology, SE-100 44 Stockholm, Sweden
[3] Karolinska Institutet, Department of Neuroscience, Stockholm, Sweden
* Correspondence: ingero@kth.se

Supplementary Materials




Figure S1: Visual appearance of exposed Cu metal coupons inclined 45° and −180° after 1, 2, 3 and 4 years in Dubai.




Figure S2: Visual appearance of exposed CuZn15 coupons inclined 45° and −180° after 1, 2, 3 and 4 years in Dubai.




Figure S3: Visual appearance of exposed CuSn4 coupons inclined 45° and −180° after 1, 2, 3 and 4 years in Dubai.




Figure S4: Visual appearance of exposed CuZn5Al5 coupons inclined 45° and −180° after 1, 2, 3 and 4 years in Dubai.