HT1 – heat treatment 1:




Image showing the indentation at one of the positions for the coarse grain HAZ area, closest to the weld fusion line.




Image showing the indentation at one of the positions for the intermediate HAZ area.





Image showing the indentation at one of the positions for the fine grain HAZ area, furthest from the weld fusion line.



General low magnification image showing the indenter locations at the HAZ.