## Supplementary Materials





**Figure S1** Interaction plots of oxidative stress indicators, genetic damage markers, cell cycle and apoptosis after exposure to Pb and Cd in TK6 cells





**Figure S2** Interaction plots of relative mRNA expressions of DNA repair genes and apoptosis pathway after exposure to Pb and Cd in TK6 cells





**Figure S3** Interaction plots of relative protein expressions of DNA repair genes and apoptosis pathway after exposure to Pb and Cd in TK6 cells.