


## Supplementary



**Figure S1** – Supplementary figure with a second set of contour images of the topographies acquired on the worn inner surfaces of four loaded specimens: a VE; b STD; c XL-75; d XL-50. The observations are very similar to the ones described for Figure 4.