



Article

Experimental Study on Neck Cutoff in Meandering River under Variable Discharges

Xinyu Wu 1,2, Xuyue Hu 3 and Xiang Zhang 2,4,5,*

- School of Water Conservancy, North China University of Water Resources and Electric Power, Zhengzhou 450045, China
- ² Key Laboratory of Lower Yellow River Channel and Estuary Regulation, MWR, Zhengzhou 450003, China
- School of Hydraulic and Environmental Engineering, Changsha University of Science and Technology, Changsha 410114, China
- College of Engineering, Ocean University of China, Qingdao 266100, China
- ⁵ Sediment Research Institute, Yellow River Institute of Hydraulic Research, Zhengzhou 450003, China
- * Correspondence: zhangxiangdut@163.com; Tel.: +86-0371-66022072

Abstract: Neck cutoff is a sudden phenomenon that occurs during the evolution of meandering rivers, but its process and mechanism remain unclear. In this investigation, the neck-narrowing process before cutoff, the formation of a new river, and the appropriate conditions for cutoff under constant and variable discharges were studied using experimental methods in a laboratory flume. The results indicated that bank erosion upstream and downstream of the neck was the main factor that triggered cutoff, regardless of whether the discharge changed. The sinuosity of the model river was approximately 7, the ratio of the neck width to the average river width reached approximately 0.43, and the experimental material was nonuniform natural sand. Under the conditions that the unit width discharge ranged from 0.0039 to 0.0069 m²/s and the longitudinal gradient was 1‰, neck cutoff could occur after sufficient bank erosion. When neck cutoff was imminent, the sinuosity of the channel increased and the channel rotated downstream. After neck cutoff, the formation of a new river experienced three stages, namely, the short-term longitudinal scouring stage, the long-term horizontal widening stage, and the long-term transverse widening and normal slow development stage. The discharge resulting in neck scouring was the effective discharge contributing to the cutoff, and this discharge directly affected the cutoff time and position. We attempted to explain the factors leading to neck cutoff from an energy consumption perspective. Neck cutoff was a sudden phenomenon that occurred when the energy consumption of a meandering river increased to its maximum value upon entry to the recession stage from the relative equilibrium stage. To a certain extent, this study is significant in understanding river evolution and neck cutoff.

Keywords: meandering river; neck cutoff; variable discharge; bank erosion; stream power



Citation: Wu, X.; Hu, X.; Zhang, X. Experimental Study on Neck Cutoff in Meandering River under Variable Discharges. *Water* **2023**, *15*, 841. https://doi.org/10.3390/w15050841

Received: 5 December 2022 Revised: 14 February 2023 Accepted: 20 February 2023 Published: 21 February 2023



Copyright: © 2023 by the authors. Licensee MDPI, Basel, Switzerland. This article is an open access article distributed under the terms and conditions of the Creative Commons Attribution (CC BY) license (https://creativecommons.org/licenses/by/4.0/).

1. Introduction

The interaction between water flow and sediment in natural rivers leads to the scouring or sedimentation of riverbeds, resulting in different channel forms, such as meandering, straight, wandering, and branching channels [1–3]. A meandering river is a typical channel form in alluvial plains. Spiral flow at the river bend promotes the deposition of convex banks and erosion of concave banks [4]. Thereafter, the sinuosity of a river bend continues to increase until cutoff occurs [5–8]. Therefore, meandering rivers in alluvial plains undergo a cyclical evolution process involving formation, development, cutoff, and new bend formation; notably, the lateral creep and migration of bends promote a gradual increase in sinuosity until cutoff occurs. Cutoff is a sudden event during the evolution of meandering rivers [9] that rapidly shortens the river length and limits the sinuosity and morphological complexity [10,11]. Natural cutoff phenomena include chute cutoff and neck cutoff, with the former being more frequently observed in many rivers, as reported in many studies [11–13].

Water 2023, 15, 841 2 of 16

The chute cutoff phenomenon generally indicates that the beach on a convex bank of a river bay is cut, and the hydrodynamic axis deviates from its original position. Chute cutoff generally occurs during high-flow periods [14]. This phenomenon may occur through the enlargement of swales, headcut extension during locally induced flooding, and downstream extension of an embayment during a sequence of floods [15]. Backwater, the inertia and direction of the channelized flow, and the floodplain topographic heterogeneity could also lead to chute cutoff [16,17].

Neck cutoff can occur after the sinuosity of a river bay reaches a critical value; the distance between upper and lower river channels is smaller than the river width, and the river bay shrinks to form a neck [18,19]; after encountering flood conditions or continuous bank collapse, the neck is washed away to form a new channel [20,21]. Due to different conditions of water and sediment and the composition of riverbank material, the occurrence modes and processes of neck cutoff also vary [9]. According to the causes of cutoff, neck cutoff can be divided into three modes: bank collapse mode, punching mode, and string groove mode [9]. In the bank collapse mode, the reason for cutoff is that the banks on both sides of a neck section collapse, or the bank on one side collapses. In punching mode, the floodplain current scours and forms new grooves. In string groove mode, the first flood scours the floodplain to form a series of gullies, and subsequent floods continue to scour along the formed series of gullies and can mainly be traced to the source.

The increased discharge during a flood period is the main factor in some rivers [22]. High-water-level floods may cause scouring of floodplains in the neck section, resulting in neck cutoff and current penetration [22,23]. However, studies also reported that increased discharge does not necessarily lead to cutoff, and cutoff does not always occur during a flood period with the highest flow [24]. Ref. [25] revealed the morphological characteristics, the degree of development of river bays, and the cycle and location of cutoff through the temporal and spatial changes in channel morphology and the sediment deposition process over 15 years. They found that the highest flow levels during a flood period did not exert the greatest impact on river evolution and cutoff. The inhomogeneity of river bank material and the increase in the local water surface gradient during a flood period may also be major factors [26]. There exists no consensus on the reasons for neck cutoff, and the study of the neck cutoff process and mechanism is an important issue in the field of riverbed evolution.

At present, chute cutoff was successfully realized in the laboratory, but neck cutoff has not been realized. The reason is that neck cutoff occurs in high-sinuosity channels that cannot be successfully prepared in the laboratory. The formation of meandering rivers is related to water flow conditions [27–29], sediment conditions (the content ratio of coarse and fine sand) [30–33], boundary conditions [34–36], and vegetation [37–44]. It is extremely difficult to experimentally coordinate the influence of various factors and shape a highly meandering channel [4,27]. At present, the sinuosity of meandering rivers established in laboratories is generally lower than 2, which cannot meet the morphological conditions for neck cutoff. Therefore, it is feasible to excavate an initial channel with a high sinuosity in a flume and apply different water flow conditions [45,46].

As a system, a river inherently contains energy, and many researchers found a relationship between the stream power and river evolution [47,48]; for example, the relationship between the stream power and sediment transport [49–51], and the effect of stream power on riparian vegetation [52]. In this investigation, the process of neck cutoff with a reduced geometric scale under constant and variable discharges was experimentally studied. We also attempted to explore the critical conditions for neck cutoff based on variation in the stream power per unit length in order to improve theoretical understanding of the process and mechanism of natural cutoff in meandering rivers.

2. Experiment Setup

2.1. Experimental System

Experiments were performed in a concrete wide-body flume, which was designed and constructed from May 2016 to May 2017. The layout of the flume system is shown in

Water 2023, 15, 841 3 of 16

Figure 1a. The wide-body flume was 25 m long, 6 m wide, and 0.4 m deep. The bottom of the flume was horizontal, and the experimental section was 21.5 m long. The front end of the flume was provided with an isosceles trapezoid-shaped forewater storage pool. The upper bottom was 2.2 m long, and the lower bottom was 6.0 m long, 2.2 m high, and 0.6 m deep. A rectangular pool with a length of 1.8 m, a width of 6.0 m, and a depth of 0.4 m was installed behind the forewater storage pool. The main function of the rectangular pool was to stabilize the water flow. After the water flow entered the forewater storage pool, it reached the rectangular pool through a grid and was discharged through the round pipe outlet. The end of the flume was provided with a sand-settling tank and a tailwater tank. The sand-settling tank was 2.0 m long and 6.0 m wide, and the tailwater tank was 1.5 m long and 6.0 m wide. The tailgate was 30 cm wide and 10 cm deep and was set at the center of the flume tail. An LDG electromagnetic flowmeter (nominal diameter DN80) was used to control the flow; the sensor coefficient was 0.8759, and the accuracy class was 0.5. Adjusting the valve of the water inlet pipe could change the reading of the electromagnetic flowmeter to control the discharge. Sediment with a thickness of 20 cm was laid in the flume before the experiment, and the sediment adopted was nonuniform natural sand. The median particle size was $d_{50} = 0.327$ mm, and the non-uniformity coefficient was $\varphi = 1.413$. The particle size distribution measured with a Mastersize 2000 laser particle size analyzer is shown in Figure 1b.




Figure 1. (a) Experimental system and (b) particle size distribution curve.

2.2. Method

We adopted a generalized model approach using a laboratory flume. The plane shape of the initial channel referred to Qigongling Bend, which is a highly curved channel at the end of the lower Jingjiang River in the middle reaches of the Yangtze River, with a sinuosity of approximately 7. Qigongling Bend (Figure 2a) was scaled down via a plane scale factor of 1:2500. The cross-section of the initial channel was rectangular, and the channel depth was 10 cm. A schematic diagram of the experimental system is shown in Figure 2b. Before conducting the experiment, sediment was first leveled into a flat bed surface with a certain gradient, and control points were then set in the flume, while the initial channel was excavated. During the experiment, the water flow initially entered the forewater storage pool via a pump, reached the river channel through a fixed water inlet at the front of the flume, and then flowed out through the tailgate into the tailwater pond. Washed sediment was captured in a sand-settling tank and recycled in the next experiment. To ensure that the water outlet could smooth the resulting water flow and reduce scouring near the water outlet, an energy dissipation grille was arranged below the water outlet.

Water 2023, 15, 841 4 of 16




Figure 2. (a) The setup of the experiment was based on Qigongling Bend, a highly curved channel at the end of the lower Jingjiang River in the middle reaches of the Yangtze River, with a sinuosity of approximately 7. (b) Overall schematic diagram of the experimental system. (c) Enlarged schematic diagram of neck width W_{nc} , which was the shortest channel width through the cutoff position; points A and B were possible cutoff locations, and the neck width was the length of section MN. (d) Schematic diagram of the new river width W_{nr} formed after cutoff.

There were a total of 7 bends, numbered B1–B7, from upstream to downstream. A total of 34 measurement sections were arranged from upstream to downstream along the river channel (Figure 2b), at intervals ranging from 0.42 to 2.0 m. The sections are represented by a capital letter S followed by a number; for example, section 7 is denoted as S7. The interval from S7 to S26 constituted the studied area; the length was 12.8 m, the average river width was 0.51 m, and the average width-to-depth ratio of the cross-section was 4.38. The researched channel segment was divided into 3 areas: the area upstream of the cutoff position (S7-S13), the bend area (S13-S21) where cutoff occurred, and the downstream area (S21–S26). The time t of the neck cutoff occurrence was defined as the period from the start of the experiment to when the upstream and downstream flow of the neck just connected and the neck width reduced to 0. The ratio of the narrowest part of the neck to the mean river width was 0.43. Since the cutoff position was uncertain, the neck width W_{nc} was defined as the shortest channel width through the cutoff position. For example, points A and B in Figure 2c were the cutoff positions in two runs, and the shortest width W_{nc} passing through these two points was the neck width. The upstream scouring distance of the neck section was expressed as W_u , and the downstream scouring distance was expressed as W_d . For example, in Figure 2c, the distance from point A to point M was W_u , and the distance from point A to point N was W_d . The rate at which the neck width decreased over a period was represented by the parameter M_D . The new channel width W_{nr} was defined as the shortest distance between the left and right banks of the new channel, as shown in Figure 2d. The widening rate of the new river after cutoff was denoted by M_n .

We designed 3 runs. The initial river topography remained the same, and the water flow conditions differed, as summarized in Table 1. Re is the Reynolds number, which is a parameter that reflects the flow pattern, and its physical meaning is the contrasting relationship between the action of inertial force and viscous force. The initial gradient in each run was the same, and S_r was set to 1.0%, which agrees with the conditions of natural meandering rivers. With reference to the change in natural river flow, the flow cycle process was designed in combination with the flow needed for sediment start. The discharge in RUN1 was constant at 2.0 L/s, and the discharges in RUN2 and RUN3 are shown in Figure 3. RUN2 first used a low-discharge cycle (1.0–1.5 L/s, each discharge lasted 8 h), and finally a high-discharge circulation (1.0–3.5 L/s, each discharge lasted 6 h). If cutoff still did not occur after the high-discharge cycle was completed, the cycle was continued.

Water 2023, 15, 841 5 of 16

The high-flow process was repeated twice, and the experiment lasted 160 h. RUN3 only exhibited a high-discharge cycle, the cycle was repeated twice, and the whole experimental process lasted 84 h.

| Table | 1. | Experimental | runs. |
|-------|----|-----------------|------------|
| IUDIC | 1. | LAPCITITICITIAL | · i ui io. |

| RUN | Initial Slope S_r | Discharge Q (L/s) | R_e | Duration t (h) |
|-----|---------------------|----------------------|-----------|----------------|
| 1 | 1.0% | Constant | 7473-8315 | 85.45 |
| 2 | 1.0‰ | Low-middle-high-high | 1454-5157 | 160 |
| 3 | 1.0% | High-high | 1436–5369 | 84 |




Figure 3. Variable discharges in (a) RUN2 and (b) RUN3.

When the amount of water and sediment in an alluvial river does not greatly vary, the stream power per unit length is related to whether river evolution reaches a relative equilibrium state. As a component of river evolution, cutoff is accompanied by changes in the river energy. This study attempted to analyze the potential energy change per unit length and unit time; notably, the per unit length stream power *P* was used to represent the hydrodynamic factor at the cutoff occurrence. *P* can be obtained as follows:

$$P = \gamma Q J \tag{1}$$

where P is the per unit length stream power, $W \cdot m^{-1}$; γ is the bulk density of water, with a value of $\gamma = 9800 \text{ N} \cdot m^{-3}$ in general; Q is the discharge, m^3/s ; and J is the hydraulic gradient, which can be approximated by the gradient of the water surface. $J = (z_1 - z_2)/L$, where z_1 and z_2 are the water levels of two sections; L is the distance between the two sections.

In addition, the response of the channel to the occurrence of cutoff was analyzed. The main analysis contents included the water surface gradient S and average shear stress τ . The average shear stress τ is calculated as follows:

$$\tau = \gamma h J_r \tag{2}$$

where τ is the average shear stress, N·m⁻²; γ is the bulk density of water, with a value of $\gamma = 9800 \text{ N·m}^{-3}$ in general; h is the average water depth, m; and J_r is the gradient of the riverbed, which is considered equal to the water surface gradient.

2.3. Data Collection

Six HIKVISION DS-2CD3T45D-I3 video recorders (4 million pixels) were installed directly above the centerline of the flume at a height of 7 m from the bed surface to record plane shape changes. The lens distortion error was 0.12 m, and the obtained photos were corrected with Photoshop software. The distance between the video recorders was 2.89 m, and the coverage of each camera was 3.56 m. Except for the 1.44 m range at the front end of the flume, which was not covered, the rest of the area until the tailgate was covered by video cameras. The total length covered by installed video cameras reached 20.06 m.

Water 2023, 15, 841 6 of 16

An automatic vehicle that could move forward and backward was installed above the flume, as shown in Figure 1a. A metal scraper that could be adjusted up and down was installed in front of the automatic driving vehicle, and a stylus that could be moved left and right was installed in the back. The metal scraper was used to level the sand, and the metal scraper was raised to a certain height at 2 m intervals from the tailgate to upstream according to the preset gradient. The stylus was used to measure the water level, water depth, and topography of the cross-section, with an accuracy of 0.1 mm. Channel shape control points were set at intervals of 0.5 m along the longitudinal direction of the flume, additional control points were added at locations where the river channel shape greatly changed, and a total of 110 control points were established.

During the experiment, changes in the hydrodynamic conditions and river morphology were observed. The water level and water depth in each cross section were measured every 6 to 12 h before cutoff, and the water level along B3 to B4 was measured when cutoff was about to occur. The initial topography was measured before the experiment. If a cutoff phenomenon occurred during the experiment, the water flow was stopped, and the topography at cutoff occurrence was measured. After the measurements, the experiment was continued. When a new channel was formed after cutoff and entered a relatively stable stage, the river width no longer varied, and the river bank no longer retreated, the experiment was stopped and the final topography was measured.

3. Results and Analysis

3.1. Neck Width Change before Cutoff

All three runs exhibited cutoffs, but the position, time, and neck width varied. In RUN1, the cutoff position was biased toward the downstream area; at 0.32 m downstream of S13, the neck width W_{nc} was 0.29 m. The cutoff positions in RUN2 and RUN3 were similar, only 0.055 m apart. The cutoff position in RUN2 was 0.029 m upstream of S13, and the neck width W_{nc} reached 0.26 m. The cutoff position in RUN3 occurred 0.026 m downstream of S13, and the neck width W_{nc} was 0.24 m. Under constant discharge, the cutoff time in RUN1 was the shortest, at 50.45 h, while the cutoff times in RUN2 and RUN3 were longer, at 131.5 and 63 h, respectively. Before cutoff, the variation in neck width W_{nc} over time is shown in Figure 4, and the reduction rate of the neck width M_D during different periods is shown in Figure 5.




Figure 4. Temporal variations in the neck width W_{nc} before cutoff.

Water 2023, 15, 841 7 of 16




Figure 5. Reduction rates for the neck width M_D during different periods with (**a**) RUN1, (**b**) RUN2, and (**c**) RUN3; the variation in M_D was closely related to the discharge and increased to different degrees when approaching cutoff in all three runs.

Although the cutoff position, neck width, and time in the three runs differed, the change trend of W_{nc} was similar, and W_{nc} gradually decreased overall. During the first few hours, due to riverbank collapse, M_D was large, and the change in M_D during the subsequent period was closely related to the discharge. Under constant discharge, M_D was small in RUN1 and sharply increased when approaching cutoff. In RUN2 and RUN3 under the condition of varied discharge, after the discharge increased or decreased, M_D accordingly increased or decreased, respectively, and M_D also sharply increased when cutoff was imminent. In addition, at a discharge of Q < 2.0 L/s, M_D was almost zero. By analyzing the discharges and times of cutoff in RUN2 and RUN3, it was found that cutoff occurred during medium- and high-discharge periods, and the medium- and highdischarge durations before cutoff were also similar. In RUN2, the discharge at cutoff occurrence reached Q = 3.0 L/s, and the duration of the $Q \ge 2.0$ L discharge was 45.5 h. In RUN3, the discharge at cutoff occurrence was Q = 3.5 L/s, and the $Q \ge 2.0$ L/s discharge persisted for 45 h. Under the same initial topography, the cutoff times in RUN2 and RUN3 were shortened by 4.95 h and 5.45 h, respectively, under varied discharge conditions, which were 9.8% and 10.8% shorter, respectively, than that in RUN1 under a constant discharge.

At cutoff, the upstream and downstream scouring distances of the neck are shown in Table 2. The upstream scouring distances W_u of RUN1 and RUN3 were less than the downstream scouring distance W_d ; W_u/W_d were 0.93 and 0.62, respectively. In RUN2, W_u was greater than W_d , and W_u/W_d was 2.71. Experiments showed that W_u and W_d were closely related to the cutoff position. The closer the cutoff position was to the downstream, the greater the scouring distance W_d .

| Table 2. Scour distance | s upstream and | downstream of | the neck. |
|--------------------------------|----------------|---------------|-----------|
|--------------------------------|----------------|---------------|-----------|

| Run | W_u (m) | W_d (m) | W_{nc} (m) | Cutoff Location | W_u/W_d |
|-----|-----------|-----------|--------------|-----------------------------|-----------|
| 1 | 0.140 | 0.150 | 0.290 | 0.320 m downstream from S13 | 0.93 |
| 2 | 0.190 | 0.070 | 0.260 | 0.029 m upstream from S13 | 2.71 |
| 3 | 0.092 | 0.148 | 0.240 | 0.026 m downstream from S13 | 0.62 |

3.2. Change in the Water Level Difference and Stream Power before Cutoff

S13 and S21 in RUN2 and RUN3 were selected to analyze the water level and water level difference between the upstream and downstream sections of the neck. The variation process of the water level over time in S13 and S21 is shown in Figure 6a, and the variation process of the water level difference over time is shown in Figure 6b. The variation trends of the water level and water level difference upstream and downstream of the neck in the two runs were the same. Before cutoff, the water level and water level difference fluctuated over time. When cutoff occurred, the water level difference reached the maximum value and then sharply declined, even reaching a negative value, and the downstream water

Water 2023, 15, 841 8 of 16

level was higher than the upstream water level. The reason for this was that upon cutoff occurrence, the discharge was high, the water flow turbulence intensity was high, stagnant water was formed downstream, and the upstream water level decreased. After cutoff, the water level difference still fluctuated. At the end of the experiment, the water level difference returned to a positive value, and the downstream water level was lower than the upstream water level.




Figure 6. Variation in the **(a)** water level and **(b)** water level drop from upstream to downstream of the neck.

The change process of the stream power per unit length P at B4 over time during the period from the start of the experiment to cutoff occurrence is shown in Figure 7. The value of P correspondingly fluctuated with the discharge, but the overall trend was increasing. When cutoff occurred, the P values in RUN2 and RUN3 increased to maximum values, namely, $P = 0.109 \text{ W} \cdot \text{m}^{-1}$ and $P = 0.101 \text{ W} \cdot \text{m}^{-1}$, respectively, and the P values in these two runs were almost equal, as indicated in Table 3. The critical sinuosity and rotation angle at B4 when cutoff occurred are provided in Table 4. In the three runs, the critical sinuosity at B4 increased to 6.71, 7.09, and 7.11, which were 3.79%, 5.89%, and 1.16% higher, respectively, than those in the initial state. In the three runs, bend B4 rotated downstream at an angle of 11° .




Figure 7. Temporal variation in the stream power per unit length.

Water 2023, 15, 841 9 of 16

| RUN | γ (N·m ⁻³) | Q (m 3 /s) | Water Head (cm) | Distance (m) | J | $P (W \cdot m^{-1})$ |
|-----|-------------------------------|-----------------|-----------------|--------------|---------|----------------------|
| 1 | 9800 | 0.0020 | 2.07 | 7.667 | 0.00270 | 0.0530 |
| 2 | 9800 | 0.0030 | 1.85 | 5.355 | 0.0035 | 0.1097 |
| 3 | 9800 | 0.0035 | 1.58 | 5.355 | 0.0030 | 0.1012 |

Table 4. Sinuosity and rotation angle of bend B4 upon cutoff occurrence.

| RUN - | | Sinuos | - Angle of Rotation Downstream (°) | |
|-------|---------|--------------------|------------------------------------|------------------------------------|
| KUN | Initial | Initial Cutoff Inc | | - Angle of Rotation Downstream () |
| 1 | 6.47 | 6.71 | 3.79 | 11 |
| 2 | 6.69 | 7.09 | 5.89 | 11 |
| 3 | 7.03 | 7.11 | 1.16 | 11 |

The experiments revealed that the main factor that caused cutoff was the scouring of river banks on both sides of the upper and lower sides of the neck. Medium and high discharges significantly contributed to cutoff, and cutoff occurred during high-flow periods. The effective discharge was defined as the discharge that contributed to scouring in the neck section, and the duration of the effective discharge directly affected the cutoff time and location. The initial topography in two runs of variable-flow experiments was the same. The duration of the effective flow and the cutoff position were similar; the duration difference reached only 0.5 h, and the distance between the cutoff positions was only 0.055 m, which also verified that the experiment was repeatable. Before cutoff occurrence, the plane geometry of the river channel also changed, the sinuosity increased, and the river bend rotated downstream. In three runs, the rotated angle was the same.

3.3. Evolution of the New Channel

Within a few minutes after cutoff occurrence, a new channel rapidly developed, mainly via longitudinal scouring. During the next few hours, the new channel was mainly widened horizontally, the water-passing section expanded, and the diversion discharge through the new channel gradually increased. Subsequently, the width of the new channel slowly increased, and distributed discharge in the old channel gradually decreased until no flow remained. The changes in the new channel width W_{nr} and average widening rate M_n are shown in Figure 8. The comparison between the initial and final topography of the relative equilibrium after cutoff is shown in Figure 9.




Figure 8. (a) Width of the new channel W_{nr} and (b) the average broadening rate M_n and corresponding discharge during different periods.

Water 2023, 15, 841 10 of 16



Figure 9. Comparison between (a) the initial terrain and the final terrain after cutoff with (b) the topography of the relative equilibrium in RUN2 and (c) the topography of the relative equilibrium in RUN3. The white line represents the measured cross section. The yellow line on the right marks the length.

The discharge affected the M_n value but did not affect the change trend of W_{nr} . Within 1 min after cutoff occurrence in RUN1, the width of the new channel W_{nr} reached 0.101 m, and the widening rate M_n of the new channel reached 6.04 m/h. After 10 min, W_{nr} reached 0.329 m. During the experimental period t = 0-10 min, M_n was 1.334 m/h. Within the experimental duration of t = 10 min-5.5 h, M_n was 0.110 m/h, and W_{nr} increased to 0.962 m. Within the experimental duration of t = 5.5-35 h, M_n reached 0.002 m/h, and W_{nr} remained stable at 1.254 m. After cutoff, the discharge remained unchanged, and M_n gradually decreased. Within 2 min after cutoff in RUN2, the W_{nr} reached 0.20 m. After 20 min, W_{nr} reached 0.43 m. Due to the increase in the discharge after cutoff, M_n increased. After cutoff at 4.5 h, the widening rate M_n decreased to 0.02 m/h at the end of the third-stage discharge Q = 3.0 L/s, and the new channel widened by 0.84 m in total. Throughout the entire process of increasing discharge, M_n increased to 0.08 m/h, and W_{nr} increased to 0.39 m. During the subsequent reduction in discharge, W_{nr} only increased by 0.08 m, and M_n was very small, at approximately 0.005 m/h. In RUN3, the discharge decreased after cutoff, M_n continuously decreased, and the change trend of W_{nr} was similar to that under a constant discharge. When cutoff had just occurred, M_n could reach 12 m/h, and W_{nr} could reach 0.24 m within 4 min. After 3 h of cutoff, the maximum discharge had stopped, and the new channel had widened by 0.62 m in total. During the subsequent reduction in the discharge, M_n reached approximately 0.002 m/h, and W_{nr} only increased by 0.04 m.

3.4. Channel Response to Neck Cutoff

The water surface gradients within the scope of S7–S13 in the upstream area, S13–S21 in the bend area, and S21–S26 in the downstream area were represented by S_u , S_c , and S_d , respectively, and the change trends are shown in Figure 10. Before cutoff, the three gradients fluctuated with discharge, and the change trends of S_u and S_d were the same, but the change trend of S_c differed from these two trends. Before cutoff, S_c was the highest, and after cutoff, S_c sharply dropped, while both S_u and S_d increased. At t = 0–130 h before cutoff in RUN2, the three gradient fluctuation ranges were 1.1–5.0%, 2.0–4.5%, and 1.3–2.2%, respectively. When cutoff was imminent, i.e., at t = 130 h, S_c was the highest, at 3.7%, S_u was moderate, at 1.8%, and S_d was the lowest, at 1.1%. After cutoff, both S_u and S_d increased, but S_d increased more. Due to backwater in the bend area, S_c sharply decreased. Under an experimental duration of t = 136 h, S_u and S_d were 2.8% and 4.2%, respectively, which were 57.7% and 287.5% higher, respectively, than that before cutoff; meanwhile, S_c decreased to 0.4%, which was 89.4% lower than that before cutoff. At t = 0–60 h before cutoff in RUN3, the three gradient fluctuation ranges were 0.9–2.0%, 0.7–1.9%, and 0.1–1.6%, respectively. Near cutoff, i.e., when the experimental duration reached t = 60 h, S_u , S_c , and S_d were 1.0%, 1.8‰, and 0.8‰, respectively. S_c was still the highest. After cutoff (experimental duration t = 63 h), S_u and S_d increased to 1.1% and 2.6%, respectively, which were 7.1% and 247.1% higher than those before cutoff, respectively; S_c decreased to 0.1%, which was 94.7% lower than that before cutoff.

Water 2023, 15, 841 11 of 16




Figure 10. Variations in the water surface gradient during (a) RUN2 and (b) RUN3. S_u and S_d showed similar trends, while S_c had the opposite trend. After cutoff, S_c sharply dropped, while both S_u and S_d increased.

The average shear stress in the upstream area S7–S13, bend area S13–S21, and downstream area S21–S26 were represented by τ_u , τ_c , and τ_d , respectively. The variations in these three average shear stresses are shown in Figure 11. Before cutoff, the change trend of the average shear stress was the same as that of discharge. When cutoff occurred, τ_c was the highest, and τ_d was the lowest. After cutoff, τ_c sharply decreased, while both τ_u and τ_d increased. In RUN2, within t = 0–130 h before cutoff, the variation range of the three average shear forces was $0.25-1.12 \text{ N}\cdot\text{m}^{-2}$, $0.43-1.26 \text{ N}\cdot\text{m}^{-2}$, and $0.1-0.75 \text{ N}\cdot\text{m}^{-2}$, respectively. The experimental duration before cutoff was t = 0–130 h, and the shear forces in the three areas were 0.55, 1.00, and $0.38 \,\mathrm{N\cdot m^{-2}}$, respectively, of which the average shear force in the bend area τ_c was the highest. After cutoff, when the experimental duration reached t = 136 h, τ_u and τ_d increased to 0.73 and 1.24 N·m⁻², respectively, which were 31.3% and 228.9% higher than those before cutoff, respectively. Moreover, τ_c was reduced to 0.09 N·m⁻², which was 90.7% lower than that before cutoff. At t = 0–60 h before cutoff in RUN3, the three average shear stress ranges were $0.21-0.73 \text{ N}\cdot\text{m}^{-2}$, $0.15-0.95 \text{ N}\cdot\text{m}^{-2}$, and $0.02-0.79 \text{ N}\cdot\text{m}^{-2}$, respectively. Before cutoff, when the experimental duration reached t = 60 h, τ_u , τ_c , and τ_d were 0.48, 0.95, and 0.24 N·m⁻², respectively, of which τ_c was still the highest. After cutoff, when the experimental duration was t = 66 h, τ_u and τ_d increased to 0.50 and 0.85 N·m⁻², respectively, which were 5.3% and 258.6% higher than those before cutoff, respectively; τ_c was reduced to 0.03 N·m⁻², which was 96.5% lower than that before cutoff.




Figure 11. Variations in three average shear stresses during (a) RUN2 and (b) RUN3. When cutoff occurred, τ_c was the highest and τ_d was the lowest. After cutoff, τ_c sharply decreased, while both τ_u and τ_d increased.

Water 2023, 15, 841 12 of 16

4. Discussion

Similar to the experiments of Han [46] and Li [45], we also achieved neck cutoff. The observed phenomena during experimentation revealed that the external factor that caused cutoff was continuous scouring due to the flow of river banks on both sides upstream and downstream of the neck. The neck width was continuously reduced until cutoff occurred. Similar results were obtained in field observations [53]. The maintenance of meandering rivers does not require varied discharge [28]. Similarly, we found that varied discharge was not a necessary condition for the occurrence of cutoff, and continuous scouring in the neck section under medium flow could also lead to neck cutoff. The experiments indicated that medium and high discharge significantly contributed to cutoff, and cutoff generally occurred during the high-discharge period. These results are the same as those of field observations [9,10,24]. The effective discharge was defined as the discharge that contributed to the scouring of the neck section, and the duration of effective discharge directly affected the cutoff time and location. The initial topographies in the two runs of variable-discharge experiments were the same, the durations of effective discharge and the cutoff position were similar, the durations differed by only 0.5 h, and the cutoff positions were only 0.055 m apart; these results verified that the experiment is repeatable. Interesting phenomena were observed during the experiment. The scouring distance of the upstream and downstream sides of the neck was closely related to the cutoff position. The closer the cutoff position occurred to the downstream, the greater the downstream scouring distance of the neck. When cutoff occurred, the plane shape of the river channel also changed, the sinuosity increased, and the river bend rotated downstream. In three experimental runs, the river bend rotated downstream at the same angle.

This study attempted to explain the internal factors of cutoff from the perspective of energy consumption. The energy of a river system itself also changes in the evolution process, and the cutoff phenomenon, as a sudden event, is accompanied by energy changes. Therefore, the internal factor causing cutoff is the internal energy variations in the river. According to the minimum energy dissipation theory, meandering rivers can adjust any possible factors to achieve the purpose of transporting water and sediment at the minimum energy dissipation rate [54–56]. The river adjustment process can be divided into short-and long-term adjustment processes. The ultimate goal of this adjustment process is to attain a relative equilibrium state, which is a dynamic equilibrium state. When a river is adjusted to a relatively balanced state, the energy consumption rate of flow should be the minimum value, and the stream power per unit length is equivalent to the energy consumption rate [57,58]. When the river reaches a relatively stable stage, although the river energy consumption rate occasionally fluctuates, it remains constant overall.

According to the variation in the stream power per unit length *P* over time in this experiment, the relationship between the P value at the different stages during the evolution of meandering rivers and cutoff occurrence was summarized, as shown in Figure 12. The river was initially at a relative equilibrium stage $(t_1 - t_2)$, and the P value was maintained at the minimum value. At this stage, the sinuosity gradually increased, forming a river with a high sinuosity suitable for the occurrence of neck cutoff. This stage persisted for a very long time. When the boundary conditions or flow conditions changed, the relative equilibrium stage was disrupted, and the river started to readjust the boundary and flow conditions. The boundary condition of a high-sinuosity river determined that the river was adjusted toward neck cutoff, and gradually moved away from the equilibrium zone. The variation in boundary conditions greatly impacted the riverbed erosion and deposition processes, and the change in P value exhibited an increasing trend overall, although it occasionally decreased in the middle at a certain time; the increased energy consumption was mainly used to adjust the channel shape, scouring and shortening the neck section, which was referred to as the recession stage (t_2-t_3) . When the P value increased to its maximum, a sudden change occurred (at time t_3 in the figure), the neck width decreased to zero, and cutoff occurred. After cutoff occurrence, a new river channel was formed; the P value gradually decreased; and the river channel entered a new evolution period, Water 2023, 15, 841 13 of 16

evolving toward a relatively balanced stage. This stage ended quickly, and the river channel mainly adjusted its longitudinal shape. The P value was relatively large, which indicated the formation stage of a new river channel (t_3-t_4) . The widening stage of the new river occurred next (t_4-t_5) . The channel mainly adjusted the shape of the transverse section. This stage persisted for a long time, and the P value gradually decreased. When the river was adjusted to adapt to the new boundary and flow conditions, it entered a new relative equilibrium stage (t_5-t_6) , and the P value again decreased to its minimum, with no major changes. This period was also long. The P value at the new relative equilibrium stage was not directly related to that at the previous relative equilibrium stage, and they were not necessarily equal. When the new relative equilibrium stage was disrupted, the river channel again entered the recession stage. Cutoff could occur again. This cycle could be repeated. Thus, neck cutoff was a sudden event that occurred when the energy consumption of a meandering river increased to its maximum value upon entry to the recession stage from the relative equilibrium stage.




Figure 12. Schematic representation of the stream power values at the different stages of the river evolution.

5. Conclusions

Neck cutoff experiments under constant- and variable-flow conditions were conducted in a flume. The main conclusions were as follows: under controllable experimental conditions, neck cutoff could be realized. The main factor that caused cutoff was erosion of the neck due to water flow, and this erosion occurred on both the upstream and downstream banks of the neck. The variable discharge affected the channel erosion rate during a certain period but did not affect the overall trend in the neck width. Before cutoff, the change trend in the neck width and the overall change trend in the new channel width after cutoff were the same. After cutoff, the development of a new channel experienced three stages: (a) the very short-term vertical drawing stage, (b) the long-term horizontal widening stage, and (c) the long-term slow development stage (normal evolution stage). The discharge resulting in neck scouring was defined as the effective discharge, which contributed to cutoff, and this discharge directly affected the cutoff time and position. Neck cutoff is a phenomenon that occurs when the energy consumption of a meandering river increases to its maximum value upon entry to the recession stage from the relative equilibrium stage.

In natural rivers, the factors impacting cutoff are very complex, such as the material composition of the riverbank, changes in incoming water and sand, boundary conditions, and vegetation. Therefore, it is difficult to compare laboratory experiments with natural river phenomena. Even though it is highly challenging to capture the neck cutoff phenomenon of natural rivers, the conclusions of this research could still provide a reference for the study of neck cutoff events in natural rivers.

Water 2023, 15, 841 14 of 16

Author Contributions: Writing—original draft preparation, X.W.; writing—review and editing, X.Z.; project administration, X.H. All authors have read and agreed to the published version of the manuscript.

Funding: This research was supported by the Open Project of the Key Laboratory/Engineering Technology Center of the Yellow River Water Conservancy Research Institute, grant number LYRCER202203; Scientific Research Initiation Project of North China University of Water Resources and Electric Power, grant number 40830; Henan Science and Technology Project, grant number 222102330195; and Special Funds for Basic Scientific Research Business Expenses of Central-Level Public Welfare Scientific Research Institutes, grant number HKY-JBYW-2020-15 and HKY-JBYW-2023-22.

Institutional Review Board Statement: Not applicable.

Informed Consent Statement: Not applicable. **Data Availability Statement:** Not applicable.

Conflicts of Interest: The authors declare no conflict of interest.

References

- 1. Kleinhans, M.G. Sorting out river channel patterns. Prog. Phys. Geogr. 2010, 34, 287–326. [CrossRef]
- 2. Yin, X.; Liang, Z.; Chen, J.; Liu, X. River Patterns and Their Changes. J. Sediment. Res. 1999, 13–19.
- 3. Schumm, S.A. Patterns of Alluvial Rivers. Annu. Rev. Earth Planet. Sci. 1985, 13, 5–27. [CrossRef]
- 4. Güneralp, İ.; Abad, J.D.; Zolezzi, G.; Hooke, J. Advances and challenges in meandering channels research. *Geomorphology* **2012**, *163-164*, 1–9. [CrossRef]
- 5. Seminara, G. Meanders. J. Fluid Mech. 2006, 554, 271–297. [CrossRef]
- 6. Callander, R.A. River Meandering. Ann. Rev. Fluid Mech. 1978, 10, 129–158. [CrossRef]
- 7. Parker, G. On the cause and characteristic scales of meandering and braiding in rivers. J. Fluid Mech. 1976, 76, 457–480. [CrossRef]
- 8. Richang, T. Preliminary analysis of the cause of meandering river section and experimental study of bed making. *Acta Geol. Sin.-Engl. Ed.* **1963**, 29, 13–21.
- 9. Hooke, J.M. Cutoffs galore!: Occurrence and causes of multiple cutoffs on a meandering river. *Geomorphology* **2004**, *61*, 225–238. [CrossRef]
- 10. Hooke, J.M. River channel adjustment to meander cutoffs on the River Bollin and River Dane, northwest England. *Geomorphology* **1995**, 14, 235–253. [CrossRef]
- 11. Micheli, E.R.; Larsen, E.W. River channel cutoff dynamics, Sacramento River, California, USA. *River Res. Appl.* **2015**, 27, 328–344. [CrossRef]
- 12. Zinger, J.A.; Rhoads, B.L.; Best, J.L.; Johnson, K.K. Flow structure and channel morphodynamics of meander bend chute cutoffs: A case study of the Wabash River, USA. *J. Geophys. Res. Earth Surf.* **2013**, *118*, 2468–2487. [CrossRef]
- 13. Qiao, Q.; Chun-guang, L.; He-fang, J.; Ling-xiao, H.; Cheng, Y. Impact of an artificial chute cutoff on the river morphology and flow structure in Sipaikou area of the Upper Yellow River. *J. Mt. Sci.* **2021**, *18*, 3275–3290. [CrossRef]
- 14. Fuller, I.C.; Large, A.R.G.; Milan, D.J. Quantifying channel development and sediment transfer following chute cutoff in a wandering gravel-bed river. *Geomorphology* **2003**, *54*, 307–323. [CrossRef]
- 15. Constantine, J.A.; McLean, S.R.; Dunn, T. A mechanism of chute cutoff along large meandering rivers with uniform floodplain topography. *Geol. Soc. Am. Bull.* **2010**, 122, 855–869. [CrossRef]
- 16. Eekhout, J.P.C.; Hoitink, A.J.F. Chute cutoff as a morphological response to stream reconstruction: The possible role of backwater. *Water Resour. Res.* **2015**, *51*, 3339–3352. [CrossRef]
- 17. Viero, D.P.; Dubon, S.L.; Lanzoni, S. Chute cutoffs in meandering rivers: Formative mechanisms and hydrodynamic forcing. *Int. Assoc. Sedimentol. Spec. Publ.* **2018**, *48*, 201–230.
- 18. Richards, D.; Konsoer, K. Morphologic adjustments of actively evolving highly curved neck cutoffs. *Earth Surf. Proc. Land.* **2020**, 45, 1067–1081. [CrossRef]
- 19. Li, Z.; Gao, P.; You, Y.; Finotello, A.; Ielpi, A. Delayed neck cutoff in the meandering Black River of the Qinghai–Tibet plateau. *Earth Surf. Proc. Land.* **2022**, 1–12. [CrossRef]
- 20. Li, Z.; Wu, X.; Gao, P. Experimental study on the process of neck cutoff and channel adjustment in a highly sinuous meander under constant discharges. *Geomorphology* **2018**, 327, 215–229. [CrossRef]
- 21. Li, Z.; Yang, H.; Xia, J.; Zhou, M.; Wang, Y. Channel morphologic processes of a highly sinuous bend approaching neck cutoff by bank erosion in the middle Yangtze River. *Int. J. Sediment Res.* **2021**, *36*, 457–467. [CrossRef]
- 22. Gay, G.R.; Gay, H.H.; Gay, W.H.; Martinson, H.A.; Meade, R.H.; Moody, J.A. Evolution of cutoffs across meander necks in Powder River, Montana, USA. *Earth Surf. Proc. Land.* **2015**, 23, 651–662. [CrossRef]
- 23. Slowik, M. The influence of meander bend evolution on the formation of multiple cutoffs: Findings inferred from floodplain architecture and bend geometry. *Earth Surf. Proc. Land.* **2015**, *41*, 626–641. [CrossRef]

Water 2023, 15, 841 15 of 16

24. Hooke, J.M. Complexity, self-organisation and variation in behaviour in meandering rivers. *Geomorphology* **2007**, *91*, 236–258. [CrossRef]

- 25. Gautier, E.; Brunstein, D.; Vauchel, P.; Roulet, M.; Fuertes, O.; Guyot, L.; Darozzes, J.; Bourrel, L. Temporal relations between meander deformation, water discharge and sediment fluxes in the floodplain of the Rio Beni (Bolivian Amazonia). *Earth Surf. Proc. Land.* **2010**, 32, 230–248. [CrossRef]
- 26. Thompson, D.M. A Geomorphic Explanation for a Meander Cutoff Following Channel Relocation of a Coarse-Bedded River. *Environ. Manag.* **2003**, *31*, 385–400. [CrossRef]
- 27. Braudrick, C.A.; Dietrich, W.E.; Leverich, G.T.; Sklar, L.S. Experimental evidence for the conditions necessary to sustain meandering in coarse-bedded rivers. *Proc. Natl. Acad. Sci. USA* **2009**, *106*, 16936–16941. [CrossRef]
- 28. Visconti, F.; Camporeale, C.; Ridolfi, L. Role of discharge variability on pseudomeandering channel morphodynamics: Results from laboratory experiments. *J. Geophys. Res.* **2010**, *115*, 1–18. [CrossRef]
- 29. Monegaglia, F.; Tubino, M. The Hydraulic Geometry of Evolving Meandering Rivers. *J. Geophys. Res. Earth Surf.* **2019**, 124, 2723–2748. [CrossRef]
- 30. Dulal, K.P.; Shimizu, Y. Experimental simulation of meandering in clay mixed sediments. *J. Hydro-Environ. Res.* **2010**, *4*, 329–343. [CrossRef]
- 31. Van Dijk, W.M.; van de Lageweg, W.I.; Kleinhans, M.G. Formation of a cohesive floodplain in a dynamic experimental meandering river. *Earth Surf. Proc. Land.* **2013**, *38*, 1550–1565.
- 32. Peakall, J.; Ashworth, P.J.; Best, J.L. Meander-Bend Evolution, Alluvial Architecture, and the Role of Cohesion in Sinuous River Channels: A Flume Study. *J. Sediment. Res.* **2007**, 77, 197–212. [CrossRef]
- 33. Smith, C.E. Modeling high sinuosity meanders in a small flume. Geomorphology 1998, 25, 19–30. [CrossRef]
- 34. Dijk, W.M.V.; van de Lageweg, W.I.; Kleinhans, M.G. Experimental meandering river with chute cutoffs. *J. Geophys. Res.* **2012**, 117, 1–18.
- 35. Xu, D.; Bai, Y. Experimental study on the bed topography evolution in alluvial meandering rivers with various sinuousnesses. *J. Hydro-Environ. Res.* **2013**, *7*, 92–102. [CrossRef]
- 36. Song, X.; Xu, G.; Bai, Y.; Xu, D. Experiments on the short-term development of sine-generated meandering rivers. *J. Hydro-Environ. Res.* **2016**, *11*, 42–58. [CrossRef]
- 37. Eaton, B.C.; Giles, T.R. Assessing the effect of vegetation-related bank strength on channel morphology and stability in gravel-bed streams using numerical models. *Earth Surf. Proc. Land.* **2009**, *34*, 712–724. [CrossRef]
- 38. Eaton, B.C. Bank stability analysis for regime models of vegetated gravel bed rivers. *Earth Surf. Proc. Land.* **2006**, *31*, 1438–1444. [CrossRef]
- 39. Tal, M.; Paola, C. Effects of vegetation on channel morphodynamics: Results and insights from laboratory experiments. *Earth Surf. Proc. Land.* **2010**, *35*, 1014–1028. [CrossRef]
- 40. Polvi, L.E.; Wohl, E.; Merritt, D.M. Modeling the functional influence of vegetation type on streambank cohesion. *Earth Surf. Proc. Land.* **2014**, *39*, 1245–1258. [CrossRef]
- 41. Millar, R.G. Influence of bank vegetation on alluvial channel patterns. Water Resour. Res. 2000, 36, 1109–1118. [CrossRef]
- 42. Gran, K.; Paola, C. Riparian vegetation controls on braided stream dynamics. Water Resour. Res. 2001, 37, 3275–3283. [CrossRef]
- 43. Corenblit, D.; Steiger, J.; Gurnell, A.M.; Tabacchi, E.; Roques, L. Control of sediment dynamics by vegetation as a key function driving biogeomorphic succession. *Earth Surf. Proc. Land.* **2009**, *34*, 1790–1810. [CrossRef]
- 44. Tal, M.; Paola, C. Dynamic single-thread channels maintained by the interaction of flow and vegetation. *Geology* **2007**, *35*, 1651–1656. [CrossRef]
- 45. Li, Z.; Gao, P.; Wu, X. Processes of neck cutoff and channel adjustment affected by seeding herbaceous vegetation and variable discharges. *CATENA* **2022**, *208*, 105731. [CrossRef]
- 46. Han, B.; Endreny, T.A. Detailed river stage mapping and head gradient analysisduring meander cutoff in a laboratory river. *Water Resour. Res.* **2014**, *50*, 1689–1703. [CrossRef]
- 47. Kleinhans, M.G.; van den Berg, J.H. River channel and bar patterns explained and predicted by an empirical and a physics-based method. *Earth Surf. Proc. Land.* **2011**, *36*, 721–738. [CrossRef]
- 48. Lague, D. The stream power river incision model: Evidence, theory and beyond. Earth Surf. Proc. Land. 2014, 39, 38–61. [CrossRef]
- 49. Petit, F.; Gob, F.; Houbrechts, G.; Assani, A.A. Critical specific stream power in gravel-bed rivers. *Geomorphology* **2005**, *69*, 92–101. [CrossRef]
- 50. Moore, I.D.; Burch, G.J. Sediment Transport Capacity of Sheet and Rill Flow: Application of Unit Stream Power Theory. *Water Resour. Res.* 1986, 22, 1350–1360. [CrossRef]
- 51. Yang, C.T.; Stall, J.B. Applicability of Unit Stream Power Equation. ASCE 1976, 102, 559–568. [CrossRef]
- 52. Bendix, J. Stream power influence on southern Californian riparian vegetation. J. Veg. Sci. 1999, 10, 243–252. [CrossRef]
- 53. Stolum, H.H. Planform geometry and dynamics of meandering rivers. Geol. Soc. Am. Bull. 1998, 110, 1485–1498. [CrossRef]
- 54. Yang, C.T. Unit stream power equations for total load. J. Hydrol. 1979, 40, 123–138. [CrossRef]
- 55. Chang, H.H. Analysis of River Meanders. J. Hydraul. Eng. 1984, 110, 37–50. [CrossRef]
- 56. Yang, C.T.; Song, C.C.S.; Woldenberg, M.J. Hydraulic geometry and minimum rate of energy dissipation. *Water Resour. Res* 1981, 17, 1014–1018. [CrossRef]

Water 2023, 15, 841 16 of 16

57. Xu, G.; Zhao, L.; Yang, C.T. Derivation and verification of minimum energy dissipation rate principle of fluid based on minimum entropy production rate principle. *Int. J. Sediment Res.* **2016**, *31*, 16–24. [CrossRef]

58. Xu, G.; Lian, J. Changes of the entropy, the entropy production and the rate of energy dissipation in river adjustment. *Adv. Water Sci.* **2004**, *11*, 3933–4024.

Disclaimer/Publisher's Note: The statements, opinions and data contained in all publications are solely those of the individual author(s) and contributor(s) and not of MDPI and/or the editor(s). MDPI and/or the editor(s) disclaim responsibility for any injury to people or property resulting from any ideas, methods, instructions or products referred to in the content.