




















(a)















(b)















(c)















(d)















(e)















(f)















(g)











(h)





(i)






Figure S1. Trace elements concentrations in the analysed water by different categories of factors. (a) City: A—Kraków, B—Jaworzno, C—Kamienna Góra, D—Racibórz, E—Myszków. (b) Type of building: A—public building, B—house, C—flat. (c) Age of connection: A—<10 years, B—10–30 years, C—>30 years. (d) Age of tap: A—<10 years, B—10–30 years, C—>30 years. (e) Age of pipe-work: A—<10 years, B—10–30 years, C—>30 years. (f) Stagnation time: A—<1 hour,

B—>1 hour. (g) Material of connection: A—PCV, B—steel, C—galvanised steel, D—stainless steel, E—other. (h) Material of pipe-work: A—PCV, B—steel, C—galvanised steel, D—stainless steel, E—copper, F—other. (i) Material of appliance: A—steel, B—other. (j) Water rating by end-user: A—good, B—unacceptable.